

Remarkable Gloss, Perfect Shining



EC-5800 High Velocity Clear Coat



Use suitable air respirator
Refer to relevant health and safety data sheet



2

1

EC-5800

PC-5671 < 18°C
PC-5672 18°C–30°C
PC-5673 > 30°C



Pot-life at 25°C
1 hour with 5671 high velocity hardener



2 coats, 40um
Flash Off Time : No



Gravity Feed: 1.3-1.4mm
Conventional: 3.0 - 4.0 bar
RP: 1.6-2.0 bar
HVLP: 2.0 bar



Drying Time:

Temperature	Tack Free	Dry to Polish
10°C	25-30 mins	90 mins
15°C	12-15 mins	50 mins
25°C	8-10 mins	30 mins